


An exploded view diagram of a mechanical assembly. The parts are numbered as follows: 12 (a large flange with a central hole, highlighted with a red box), 12b (a small pin), 20 (a small washer), 21 (a large nut), 24 (a long pin), 25 (a small washer), 27 (a small washer), 30 (a small washer), 31 (a small washer), 55 (a bracket), and 56 (a small pin). The diagram shows the relative positions and assembly sequence of these components.

[illegible]